

Southwest Detroit Properties Windshield Site Assessment Results

Address: 230 S. Morrell

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

vegetation, small trees

Photographer(s): _____

Related Photograph Tag Numbers

<u>100-5533</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 227 S. Morrell

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Small trees, used for parking by 233 Morrell.

Photographer(s): MATB

Related Photograph Tag Numbers

<u>100-5532</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 317 S. Morrell

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: Y / N (Circle One)

Empty Lot (i.e., no structure present): Y / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5531</u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 5866 Reader

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: Y / N (Circle One)

Empty Lot (i.e., no structure present): Y / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Building debris pile MB Vegetation and sm/
medium sized trees

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5527</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 5873 Reader

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: ☒ / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Empty lot that has been fenced in by
5840 W. Jefferson (Edward Duffy & co Steel tubing)

Photographer(s): MAR

Related Photograph Tag Numbers

100-5528 _____ _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 8023 Thaddeus

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: Y / N (Circle One)

Empty Lot (i.e., no structure present): Y / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

— open lot

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100 - 5520</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 8040 Thaddeus

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Vegetation & small trees

Photographer(s): MAB

Related Photograph Tag Numbers

100-5519

Southwest Detroit Properties Windshield Site Assessment Results

Address: 8124 Thaddeus

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Used as a parking area for nearby homes

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5518</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 8361 Thaddens

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: ☒ / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: fence, above ground
pool, boat

Description of Any Environmental Concern(s) at the Address: -

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Appears lot has been fenced in and
taken over by 8365 Thaddens

Photographer(s): MTB

Related Photograph Tag Numbers

<u>100-5517</u>		

Southwest Detroit Properties Windshield Site Assessment Results

Address: 9110 Thaddus

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: Y / N (Circle One)

Empty Lot (i.e., no structure present): Y / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

— empty flat lot.

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5505</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 9116 Thaddeus

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Tall vegetation rear half of the property

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100 - 5506</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 4625 Fort St


Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: Y / N (Circle One)

Empty Lot (i.e., no structure present): Y / N (Circle One)



Description of Any Structure(s) at the Address: _____

Description of Any Environmental Concern(s) at the Address: _____

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Address doesn't exist, corner of Summit and
Fort is 4617 (Bridgewater Interiors) and 4735
(Greater Apostolic Faith Temple)

Photographer(s): mn

Related Photograph Tag Numbers

<u>100-5536</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 6155 Fort St

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: Y / N (Circle One)

Empty Lot (i.e., no structure present): Y / N (Circle One)

Description of Any Structure(s) at the Address: -

Description of Any Environmental Concern(s) at the Address: -

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Fenced into 6121 Fort (empty business)

Photographer(s): _____

Related Photograph Tag Numbers

100-5539 _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 6249 Fort

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

— Appear newly graded

Photographer(s): _____

Related Photograph Tag Numbers

<u>100-5538</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 5645 Anthen St

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

—

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5537</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 418 S. Harvey Calvary St

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

same small trees

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5529</u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 501 Crossley

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: -

Description of Any Environmental Concern(s) at the Address: -

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Medium sized trees, light vegetation

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5523</u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 8633 Dearborn

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

—

Photographer(s): MATB

Related Photograph Tag Numbers

<u>100-5517</u>	<u> </u>	<u> </u>
<u>100-5516a</u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 9057 Dearborn

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

light vegetation, couple trees

Photographer(s): MAB

Related Photograph Tag Numbers

100 - 5515 _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 5652 Harvey

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: ☒ / N (Circle One)

Vacant Property: Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: fence

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

fenced in by 5648 Harvey

Photographer(s): MB

Related Photograph Tag Numbers

<u>100-5530</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 3541 Howard

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address:

Description of Any Environmental Concern(s) at the Address:

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

some household debris

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5540</u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 8941 Keller

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

light vegetation

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5510</u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 9015 Keller

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Some debris

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100 - 5508</u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 9143 Keller

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Vegetation at rear of property.

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5509</u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 9059 Lyon

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: Y / N (Circle One)

Empty Lot (i.e., no structure present): Y / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Few trees at rear of property

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5507</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 308⁹ McKinstry

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: (Y) / N (Circle One)

Empty Lot (i.e., no structure present): Y / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Open lot

Photographer(s): _____

Related Photograph Tag Numbers

<u>100-5535</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 9139 Melville

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Some vegetation

Photographer(s): _____

Related Photograph Tag Numbers

<u>100 - 5513</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 9146 Melville

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

some vegetation

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5514</u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 9276 Melville

Residential Property: ☒ / N (Circle One)

Industrial Property: Y / ☐ N (Circle One)

Occupied Property: Y / ☐ N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): Y / ☐ N (Circle One)

Description of Any Structure(s) at the Address: Burned down structure
(home), some vegetation

Description of Any Environmental Concern(s) at the Address: -

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100 - 5511</u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 9281 Melville

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: ☒ / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

lot appears to have been fenced in by
9275 Melville

Photographer(s): _____

Related Photograph Tag Numbers

<u>100 - SS12</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 280 Harbough

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): Y / N (Circle One)

Description of Any Structure(s) at the Address: _____

Description of Any Environmental Concern(s) at the Address: _____

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Photographer(s): MAB

Related Photograph Tag Numbers

100-5516

Southwest Detroit Properties Windshield Site Assessment Results

Address: 8129 W. Jefferson

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: Y / N (Circle One)

Empty Lot (i.e., no structure present): Y / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Vegetation and some medium sized trees

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5521</u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: ⁸¹⁴¹~~2421~~ W. Jefferson

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: Y / N (Circle One)

Empty Lot (i.e., no structure present): Y / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

—

Photographer(s): MAD

Related Photograph Tag Numbers

<u>100-5522</u>		

Southwest Detroit Properties Windshield Site Assessment Results

Address: 7925 West Jefferson

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

—

Photographer(s): MAB

Related Photograph Tag Numbers

<u>100-5524</u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 6208 W. Jefferson

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

—

Photographer(s): MAD

Related Photograph Tag Numbers

<u>100-5525</u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 5822 W. Jefferson

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: Y / N (Circle One)

Empty Lot (i.e., no structure present): Y / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

old tires

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

old wood fence, debris, possible work being
conducted or homeless living on parcel,
something being burned.

Photographer(s): MAB

Related Photograph Tag Numbers

100 - 5526 _____

4/10/21
GFB

Southwest Detroit Properties Windshield Site Assessment Results

Address: 194 Summit

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: (Y) / ~~(N)~~ (Circle One)

Empty Lot (i.e., no structure present): (Y) / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: — Some

tires along the road

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

light vegetation

Photographer(s): _____

Related Photograph Tag Numbers

100-553/3 34 _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 2836 Porter St

Residential Property: Y / N (Circle One)

Industrial Property: Y / N (Circle One)

Occupied Property: Y / N (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: —

Description of Any Environmental Concern(s) at the Address: —

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Empty grass lot

Photographer(s): MTS

Related Photograph Tag Numbers

<u>100-5541</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 6420 South Street

Residential Property: Y / ☒ (Circle One)

Industrial Property: ☒ / N (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

<u>4698.jpg (H)</u>		

Southwest Detroit Properties Windshield Site Assessment Results

Address: 511 S. Schroeder

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Lori Koze

Related Photograph Tag Numbers

<u>4699.jpg (E)</u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 521 S. Post

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

4700.jpg (E) _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 516 S. Harrington

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: Multiple piles of material covered with snow.

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

4701.jpg (w) _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 546 S. Harrington

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

<u>4702.jpg (w)</u>	<hr/>	<hr/>
<hr/>	<hr/>	<hr/>
<hr/>	<hr/>	<hr/>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 605 S. Harrington

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Lori Kozel

Related Photograph Tag Numbers

<u>4703.jpg (E)</u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 728 Rademacher

Residential Property: Y / ☒ (Circle One)

Industrial Property ☒ / N (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

<u>4704.jpg (E)</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 730 Rademacher

Residential Property: Y / ☒ (Circle One)

Industrial Property: ☒ / N (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T Brown

Related Photograph Tag Numbers

<u>4705.jpg (E)</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 7841 Melville

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T. Brown: ng

Related Photograph Tag Numbers

4706.jpg (s) _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 7837 Melville

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

4707.jpg (W) (S) _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 7847 Medina

Residential Property: ☒ / N (Circle One)

Industrial Property: Y / ☒ (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: Trash can at

back of property

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Lori Kozel

Related Photograph Tag Numbers

4708.jpg (E)

Southwest Detroit Properties Windshield Site Assessment Results

Address: 585 S. Solway

Residential Property: ☒ Y / ☒ N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / ☒ N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: No structures

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Lori Kozel

Related Photograph Tag Numbers

4673.jpg (E)

Southwest Detroit Properties Windshield Site Assessment Results

Address: 440 S. Solway

Residential Property: ☒ / N (Circle One)

Industrial Property: Y / ☒ (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: No structures on lot.

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

4674 .jpg (w)

Southwest Detroit Properties Windshield Site Assessment Results

Address: 564 S. Solway

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: No structures

Description of Any Environmental Concern(s) at the Address: ~~None evident~~

Three piles of material covered by snow.

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Great deal of vegetation (approximately three feet high)

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

4675.jpg (w) _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 9276 Melville

Residential Property: Y / ☒ (Circle One)

Industrial Property: ☒ / N (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): Y / ☒ (Circle One)

Description of Any Structure(s) at the Address: Collapsed building with debris

Description of Any Environmental Concern(s) at the Address: _____

One pile of material covered with snow

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Building debris

Photographer(s): Lori Kozel

Related Photograph Tag Numbers

4676.jpg (N) _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 805 S. Green

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: No structures on lot

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

<u>4677.jpg (E)</u>	<hr/>	<hr/>
<hr/>	<hr/>	<hr/>
<hr/>	<hr/>	<hr/>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 702 S. Green

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: No structures

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Lori Kozel

Related Photograph Tag Numbers

4678.jpg f(w)

Southwest Detroit Properties Windshield Site Assessment Results

Address: 604 S. Green

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: No structures

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Great deal of vegetation (approximately three feet high)

Photographer(s): Lori Kozel

Related Photograph Tag Numbers

<u>4679.jpg (w)</u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 589 S. Green

Residential Property: ☒ / N (Circle One)

Industrial Property: Y / ☒ (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: No structures

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

<u>4680.jpg (E)</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 581 S. Green

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: No structures

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

<u>4681.jpg (E)</u>		

Southwest Detroit Properties Windshield Site Assessment Results

Address: 514 S. Green

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: No structures

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Lori & Kozel

Related Photograph Tag Numbers

<u>4682.jpg (w)</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 406 S. Green

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: No structures

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Vegetation approximately three three feet high

Photographer(s): Lori Kozel

Related Photograph Tag Numbers

4683.jpg (w) _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 739 Cottrell

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: No structures

Description of Any Environmental Concern(s) at the Address: One fire on lot

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

<u>4684.jpg (E)</u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: ~~312~~ S. Military
226 MTB

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: No structures

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Lori Kozel

Related Photograph Tag Numbers

4685.jpg (w) _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 218 S. Military

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: ☒ Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: No structures

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Lori Kozel

Related Photograph Tag Numbers

<u>4686.jpg (w)</u>	_____	_____
_____	_____	_____
_____	_____	_____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 226 S. Military
212 MTB

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present) ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: No ~~strut~~ structures

Description of Any Environmental Concern(s) at the Address: One pile of
material covered with snow

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Lori Kozei

Related Photograph Tag Numbers

4687.jpg (w) _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 304 S. Military

Residential Property: Y / ☒ (Circle One)

Industrial Property: ☒ / N (Circle One)

Occupied Property: ☒ / N (Circle One)

Vacant Property: Y / ☒ (Circle One)

Empty Lot (i.e., no structure present): Y / ☒ (Circle One)

Description of Any Structure(s) at the Address: Trailers

Description of Any Environmental Concern(s) at the Address: Trailers

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Unable to see beyond trailers located just inside
the fenceline.

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

4688.jpg (w) _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 32 341 Military

Residential Property: ☒ Y / N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property: ☒ Y / N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Lori Kozel

Related Photograph Tag Numbers

<u>4689.jpg (E)</u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 335 Military

Residential Property: ☒ / N (Circle One)

Industrial Property: Y / ☒ (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Lori Kozei

Related Photograph Tag Numbers

<u>4690.jpg (E)</u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>
<u></u>	<u></u>	<u></u>

Southwest Detroit Properties Windshield Site Assessment Results

Address: 745 Military

Residential Property: ☒ Y / ☐ N (Circle One)

Industrial Property: Y / ☒ N (Circle One)

Occupied Property: Y / ☒ N (Circle One)

Vacant Property ☒ Y / ☐ N (Circle One)

Empty Lot (i.e., no structure present): ☒ Y / ☐ N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Lori Kozel

Related Photograph Tag Numbers

4691.jpg (w)

Southwest Detroit Properties Windshield Site Assessment Results

Address: 1184 Morrell

Residential Property: ☒ / N (Circle One)

Industrial Property: Y / ☒ (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): Y / ☒ (Circle One)

Description of Any Structure(s) at the Address: No structures

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Three pieces of furniture

Photographer(s): Lori Kozel

Related Photograph Tag Numbers

4692.jpg (F)

Southwest Detroit Properties Windshield Site Assessment Results

Address: 466 S. Campbell

Residential Property: Y / ☒ (Circle One)

Industrial Property: ☒ / N (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property: Y / ☒ (Circle One)

Empty Lot (i.e., no structure present): Y / ☒ (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: Tire and debris

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Tire and debris

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

4693.jpg (E) _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 522 S. Campbell

Residential Property: Y / ☒ (Circle One)

Industrial Property: ☒ / N (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property: ☒ / ☒ (Circle One)

Empty Lot (i.e., no structure present): Y / ☒ (Circle One)

Description of Any Structure(s) at the Address: Tree and fallen trees

No structures

Description of Any Environmental Concern(s) at the Address: Tree and fallen

Trees

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

4694.jpg (w)

Southwest Detroit Properties Windshield Site Assessment Results

Address: 6402 South Street

Residential Property: Y / ☒ (Circle One)

Industrial Property: ☒ / N (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

None

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

<u>4695.jpg</u>	<u>(SN)</u>	

Southwest Detroit Properties Windshield Site Assessment Results

Address: 6410 South Street

Residential Property: Y / ☒ (Circle One)

Industrial Property: ☒ / N (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Trees and other vegetation

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

4696.jpg _____

Southwest Detroit Properties Windshield Site Assessment Results

Address: 6414 South Street

Residential Property: Y / ☒ (Circle One)

Industrial Property: ☒ / N (Circle One)

Occupied Property: Y / ☒ (Circle One)

Vacant Property: ☒ / N (Circle One)

Empty Lot (i.e., no structure present): ☒ / N (Circle One)

Description of Any Structure(s) at the Address: None

Description of Any Environmental Concern(s) at the Address: None

Description of Any Other Concerns at the Address (e.g., fences, animals, or vegetation):

Trees and vegetation

Photographer(s): Michael T. Browning

Related Photograph Tag Numbers

4697.jpg(N)

